

## EU REACH SCIP dossiers List

### EU REACH 1907/2006

The Registration, Evaluation, Authorisation and Restriction of Chemicals (REACH) Regulation within the frame of the DIRECTIVE 2008\_98\_EC - WASTE FRAME DIRECTIVE requires the identification of Substances of Very High Concern (SVHC) contained in articles above the threshold 0.1% w/w manufactured and marketed in the EU (Legal Reference EC 1907/2006). We hereby send you information related to SCIP dossiers submitted to the European Chemical Agency (ECHA) in accordance with Article 33(1) of the REACH regulation.

### Declaration:

We, ChargePoint Network declare that this EU REACH SIPC dossiers list is issued under our sole responsibility as an EU importer.

This declaration is accurate to the best of our knowledge with the information gathered to date.

DocuSigned by:



A90A946E47884A3...

Reference number	Names	Identifiers	Dossier UUID	Submission number	Submission date	Submission type
c8ad2f84-b7a6-408b-bf5f-fe713b732533	CPE250,EU,2 CABLES,DVT	99-002611-10	a6f13026-a7d6-4582-bd44-31a79b2cd6f4	KAZ058494-18	13/01/2023	update
cc67d50e-7e03-48db-88de-4301023c7f21	EXPP-PM-40KW, PRQ1	99-004701-08	9e385714-ade4-4067-9e67-c794b4cb9899	KAZ224802-41	13/01/2023	initial
366388fb-c4a0-4277-8183-901cc3b600b3	CPHM400	99-005156-02	2c1a1729-2626-473f-9292-b349f1ccc9f7	KAZ178437-23	05/01/2023	update
366388fb-c4a0-4277-8183-901cc3b600b3	CPHM400	99-005156-02	b7545c43-ce6f-416d-bc72-e684035aac4a	KAZ693526-23	05/01/2023	update
366388fb-c4a0-4277-8183-901cc3b600b3	CPHM400	99-005156-02	339aba4e-422a-4c0d-b1a0-e8d821c0789c	KAZ100990-36	05/01/2023	initial
ccbcd980-dc34-4a23-8220-7fa486cb9852	CPHM400	99-005156-01	0ab0efc9-c9d8-4c91-8ad6-2c2a6430a9b0	KAZ810887-17	05/01/2023	initial
2d7b0abc-acf5-44b6-9a32-fbe831622da4	CPHM400	99-005156-03	785baebb-1644-4cb6-9735-3df83aa53b16	KAZ969211-18	05/01/2023	initial
1d554935-fd80-4b83-a48c-d8531b22f39b	CP4120-SH-UNIT	99-003204-01	590f747e-148e-4a89-aef8-5927c2bdcaec	KAZ630971-26	04/01/2023	update
1b0441e3-c00d-4809-8d37-338013ec8fc5	CP4300,Single Port,Cabled,T2,Pedestal	99-003212-01	7f7f9038-d426-4951-8b23-c5cbd23c4901	KAZ463792-18	04/01/2023	update
fb29f63f-80aa-4c0f-8e5f-03f355080386	CP4110-SH-UNIT	99-003202-01	63b30616-4036-43b3-9c29-15d8ef26dacc	KAZ300145-45	04/01/2023	update
9d3c1b6a-3e0c-4b83-8c8e-90ecabc64c69	CPGW-EU	99-004118-01	ccf6c573-a4b2-40dd-a8da-32ec76c9778d	KAZ820644-29	04/01/2023	update
21099736-da60-4759-a357-fac8aeb7c3e6	CPH32-T2-EU	99-003012-01	6caac1a6-a88b-4ba9-9ade-9f45386538c0	KAZ323927-31	04/01/2023	update
eea15c64-5050-49a9-97e3-0acb679ba9d8	CPH32-T2	99-003002-01	bc07a0cb-c54e-490f-bc39-1778daf98c72	KAZ060472-39	04/01/2023	update
27edbddd-5719f-49bc-a47a-ea7722560d18	CP4320-MTR-UNIT	99-003206-02	cba3f9f3-ed2c-4b3b-a66b-2a3c9d2078e5	KAZ418750-23	04/01/2023	update
d14ab546-f195-408d-b83a-02cf3f147553	CPF32-T2-EU	99-004121-01	ad50b631-e8b9-49f3-b3f3-b13b962c8df8	KAZ742850-25	04/01/2023	update
31a824c4-7926-4577-89b6-e53a150f05e3	CP4110-MTR-UNIT	99-003201-02	1cb2a868-eff8-46e1-b593-567e210e5c11	KAZ241899-20	04/01/2023	update
bbfe43ea-efeb-482b-81f4-83b4b7a0eb14	CP4120-MTR-UNIT	99-003203-02	f09077c3-4145-478e-ba3e-3c891efcc779	KAZ172008-44	04/01/2023	update
a445c392-7062-497a-ba4d-36803c710dc0	CP4310-MTR-UNIT	99-003205-02	fccdd500-065d-4932-b02d-185ddb4af778	KAZ598741-14	04/01/2023	update
10655547-10a8-40ab-bf92-ea2dda35592a	CP4303-ACTK	99-003216-01	da8b1822-15a2-43f3-a017-db1bed1a2dd5	KAZ875019-21	04/01/2023	update
44ae5512-8375-48b1-8492-9ff5e11e8b6f	CP4300,Dual Port,Cabled,T2,Pedestal	99-003213-01	b572c693-ba5e-4aa5-8460-f0e60752c1d4	KAZ642017-36	04/01/2023	update

Reference number	Names	Identifiers	Dossier UUID	Submission number	Submission date	Submission type
5c44dbed-3293-444a-bdc1-4d0ebb630847	CPGW-EU	99-004122-01	a33cccd3-b8a6-4781-9b2d-90b2618e6127	KAZ576476-12	04/01/2023	update
43fca908-a44c-4aee-bf89-2616fb3a1615	CP6K-CABLE-7M-T2-32A-15118	99-005703-05	f2916374-8116-4065-9b63-25c3c172a714	JFH310032-59	22/11/2022	initial
cdc67939-4341-4570-8b38-516704a8f15e	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL CABLE-T2-32A-5.5M-15118	99-006602-05	709ceb0e-2197-4c44-9e78-efee4286ec3	JFH239811-38	22/11/2022	initial
caac0d90-ce38-4aaf-af9a-32baf4075e86	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-SHUTTER SOCKET-CABLE-T2-32A-7M-15118	99-006617-01	bc8d5220-b43c-443e-ae61-93cbb293377f	JFH365221-45	22/11/2022	initial
459ae8b6-2285-4f65-aeb4-3af7bb07f009	CP6K-CABLE-5.5M-T2-32A-15118	99-005702-05	ce9da55c-9ee9-4770-a32f-4ef3ce2c37ff	JFH689695-07	22/11/2022	initial
0f918f13-38fa-4e8a-b013-82318b243f26	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-SING SHUTTER SOCKET	99-006611-01	e3016b37-74ef-4699-a5fc-b2ef64c8b2f9	JFH390241-48	22/11/2022	initial
254415b3-d222-4278-b266-3521fb098e7e	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL SHUTTER SOCKET	99-006610-01	11d17f6a-b2a1-4a9d-a4f1-f7adfe86d473	JFH076034-45	22/11/2022	initial
fd9f5816-e0be-43e4-8279-4296caa0e49	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL SOCKET	99-006605-05	d1dd2864-0266-40ec-8e94-ee9c9f6dcd7f	JFH237137-39	22/11/2022	initial
c3674776-25de-4540-96f2-8288e9983b6f	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-SING CABLE-T2-32A-7M-15118	99-006616-01	dd635932-4374-42ef-9ee1-771905af45d4	JFH081638-44	22/11/2022	initial
d2bd9a65-f8af-4398-a8a1-a597c8802e52	CP6K-SOCKET-15118	99-005701-02	b9b30a68-ec6a-454b-b8af-36d81bac1845	JFH198648-25	22/11/2022	initial
ad3bf6a4-6643-4cd4-b5ef-3d9035906f92	CP6K-SOCKET-SHUTTER-15118	99-005707-02	4e9ec8c3-2fec-4517-bf30-84c954b5f3e3	JFH589098-12	22/11/2022	initial
03c928c9-60da-4fe9-ab7a-bf86c844eff4	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-SHUTTER SOCKET-CABLE T2-32A-5.5M-15118	99-006618-01	3f5577e8-41c9-472d-916b-a73034c9faf3	JFH914515-35	22/11/2022	initial
6d082581-76bc-4bb6-b09c-cebf6ab957d3	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL CABLE-T2-32A-7M-15118	99-006615-01	a4d6c899-6d6e-401b-8a26-8d0155a29db6	JFH505824-38	22/11/2022	initial
13ebbe22-25be-4984-bdd6-e4655f718650	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-	99-006613-01	5e2b8673-e417-490b-85c4-618cd477e6f2	JFH135124-50	22/11/2022	initial

Reference number	Names	Identifiers	Dossier UUID	Submission number	Submission date	Submission type
	CPIM-SING CABLE-T2-32A-5.5M-15118					
49efec5f-8ccb-42ff-8955-f5843b0d4a98	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-SING SOCKET	99-006614-01	9aa97107-ff6c-4291-9908-37acb878fa84	JFH411844-43	22/11/2022	initial
4c9055d6-bdb7-4093-80bc-e1e4ca03414f	CPIM1000	99-005607-05	312002e9-6c11-4ac1-8018-a561e00287b0	UXC096371-93	21/11/2022	initial
a445c392-7062-497a-ba4d-36803c710dc0	CP4310-MTR-UNIT	99-003205-02	872c6af1-040f-4d2c-a571-9be8966efcee	KQA762137-20	14/06/2022	update
31a824c4-7926-4577-89b6-e53a150f05e3	CP4110-MTR-UNIT	99-003201-02	b1bc9f14-5d1f-47d9-9cd9-70ad4e79fae6	KQA280677-19	14/06/2022	update
223e31c6-0f41-4ad9-a6b7-974f2ddf3a45	EXPP-PM	99-002609-07	d9b1b2a9-7f29-4c9e-a497-80aa12fe9b27	KQA349335-16	14/06/2022	initial
c34a44e0-0c31-4d5a-932c-f6839c47ac44	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL SOCKET	99-006605-04	da825777-6342-4573-b7e4-6ac94261b693	KQA083108-35	14/06/2022	initial
f3128ea0-db2f-461f-aeda-511cd2ad5e7f	CP4120-UNIT	99-003203-01	db90fbb5-63fe-4144-b5c1-7eab0bcea32a	KQA595838-07	14/06/2022	update
d4900659-43c3-4878-a11e-7dddab201a2f	EXPP-PM	99-002609-11-BY	8a01cb60-ea4e-4008-827d-e5312535e824	KQA724216-24	14/06/2022	initial
c8ad2f84-b7a6-408b-bf5f-fe713b732533	CPE250,EU,2 CABLES,DVT	99-002611-10	96408eec-596c-4989-b04d-232c8ac45a1d	KQA412944-24	14/06/2022	initial
27edbddd-5719f-49bc-a47a-ea7722560d18	CP4320-MTR-UNIT	99-003206-02	231aa408-71f4-45a1-8a6f-94ceaab25835	KQA097604-25	14/06/2022	update
01ae45f2-8d1f-423a-8fcc-fee167a8ffe	CP4320-UNIT	99-003206-01	6d37b8b7-e470-42a0-930c-fe9cc66578e9	KQA227300-35	14/06/2022	update
4406f5da-74fc-4a47-bc1e-e8debcdcb48a	EXPP-PM	99-002609-04	9258f1dd-0e58-4f95-9be3-21c061092d73	KQA930200-35	14/06/2022	initial
bbfe43ea-efeb-482b-81f4-83b4b7a0eb14	CP4120-MTR-UNIT	99-003203-02	d8788ea6-8a72-4ef8-b2d7-6fed629978c3	KQA160595-22	14/06/2022	update
9468c7a1-594c-41e5-99e5-0b4ad937c73e	EXPP-PM	99-002609-11	f10561ad-0e51-40c6-8949-d10b028be0e8	KQA979206-07	14/06/2022	initial
20a48684-a6db-4dfb-9434-5fff13b623c4	CPE250,EU,CCS2,CH D,BFS	99-002611-09	2c7ed96e-7e4c-4274-9e58-91dde46b0b69	KQA271866-19	14/06/2022	initial
21099736-da60-4759-a357-fac8aeb7c3e6	CPH32-T2-EU	99-003012-01	73bcc2ce-7eba-432d-a504-cab43f27baee	KQA354593-13	14/06/2022	update
e4e54e2d-c9d5-4fe1-bdc0-73b3e7acf391	CPE250-AUXPOWER-F	99-002803-01	93b45b59-598b-484d-8c95-74694d970cd7	KQA634602-27	14/06/2022	initial
e5774b6e-bdce-4d78-ac2f-14bd7fe4b340	CPE250, EU, CCS2/CHD, MB	99-002716-08	1e763d6a-2d9d-4ad9-874f-a6efdc44ab2	KQA603592-15	14/06/2022	initial

Reference number	Names	Identifiers	Dossier UUID	Submission number	Submission date	Submission type
53b36ca2-bfcd-403f-a1f3-84d618ea5fed	CPE250, EU, 2 CABLE, IV SIGNS	99-002639-02	36949495-d34a-4166-b287-92ac4ecdb539	KQA572162-22	14/06/2022	initial
1d554935-fd80-4b83-a48c-d8531b22f39b	CP4120-SH-UNIT	99-003204-01	50c5830d-76ad-4540-9f5d-be3e4a6c10f2	KQA229121-28	14/06/2022	update
fb29f63f-80aa-4c0f-8e5f-03f355080386	CP4110-SH-UNIT	99-003202-01	0b970398-3841-4ce7-bbdf-4cf5f81edafb	KQA339033-22	14/06/2022	update
c0713c17-c9e7-4cb0-b785-c9ab0f90ab4d	CPE250, EU, CCS1/CCS2, MB	99-002713-02	a39113fe-6381-42c5-a266-a1a5c6d75f2d	KQA308944-15	14/06/2022	initial
b003f674-624b-463a-853c-58cfa83cadc5	CPH32-T2-L8	99-003008-01	a500e5d2-c67c-4a76-b374-3c606c5c2603	KQA367060-20	14/06/2022	initial
eea15c64-5050-49a9-97e3-0acb679ba9d8	CPH32-T2	99-003002-01	e9344463-4210-4b81-ac23-525411894cfb	KQA702161-26	14/06/2022	update
444e5512-8375-48b1-8492-9ff5e11e8b6f	CP4300,Dual Port,Cabled,T2,Pedestal	99-003213-01	3f5d72dd-4793-4f3e-997a-e2fd28de7f0c	KQA155610-33	14/06/2022	update
1b0441e3-c00d-4809-8d37-338013ec8fc5	CP4300,Single Port,Cabled,T2,Pedestal	99-003212-01	19b5f470-0979-42aa-a613-aa5367000066	KQA549544-09	14/06/2022	update
e6b0c35f-b243-41ed-929d-0326f45a8bdd	CPE250, EU, CCS2/CHD, MB	99-002716-02	cded1f6a-c459-459c-819e-d98792ef6ff0	KQA582227-23	14/06/2022	initial
2d564807-dd9f-4a2d-a924-77744f7098b4	CP4310-UNIT	99-003205-01	257bb91d-0e2d-4875-a759-473821223cf4	KQA393201-34	14/06/2022	update
f81bba22-769c-437e-bb8c-75708e9e3c2f	EXPP-PM	99-002609-10	ccabdc7f-1d77-4844-a172-9aa590e4bb6d	KQA408726-17	14/06/2022	initial
3c5f19a2-7baa-4de9-b2a9-cac8740ede0	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL CABLE-T2-32A-5.5M-15118	99-006602-04	3efaf393-7203-4d4c-8251-b994701e66dd	KQA457385-07	14/06/2022	initial
418797d6-1263-45c2-9063-b601f673adbf	CPE250, EU, 2 CABLE CCS1/CCS2,DVT	99-002703-08	5632a6ec-f913-4a1f-9b44-fed87fcb9db0	KQA415070-25	14/06/2022	update
c9afd0c-0feb-4556-a57f-56931c9086a1	CPH32-T2-L6	99-003006-01	ad5c368f-cb45-4838-abb2-fb9f748ea041	KQA035833-28	14/06/2022	initial
891f50c8-ba7f-4334-a1aa-5c55793359f0	EXPP-PB1000-AUXPOWER	99-004414-01	ac3c049f-6256-42bb-a2db-802483127ac6	KQA347408-22	14/06/2022	initial
e0bb5db6-a3a0-48cb-acf7-8ad5c90267cb	CP4110-UNIT	99-003201-01	02cf2484-1fbd-4eed-a712-9023f0ae4774	KQA596985-97	14/06/2022	update
48e9ca93-7976-4986-b02a-980f65b2e419	AC MODULE V4, PANTHER	99-005607-04	d39aaba0-ae51-4ed8-8e70-658c2426b000	KQA734450-19	14/06/2022	update
a97d907d-38e7-443b-b889-65e7b2f8b5b3	CPE250, EU, CCS2/CHD, MB	99-002716-07	96188e63-9bc1-4a92-b874-b19cdc58e277	KQA226824-24	14/06/2022	initial
10655547-10a8-40ab-bf92-ea2dda35592a	CP4303-ACTK	99-003216-01	75e854ac-8d83-487b-a4ca-ea04c77d4ea1	KQA657936-06	14/06/2022	update

Reference number	Names	Identifiers	Dossier UUID	Submission number	Submission date	Submission type
d14ab546-f195-408d-b83a-02cf3f147553	CPF32-T2-EU	99-004121-01	24e18691-aadd-451f-a732-d5ef9ab90498	JZB074262-09	26/01/2022	update
a445c392-7062-497a-ba4d-36803c710dc0	CP4310-MTR-UNIT	99-003205-02	dbefdc54-b869-4fe0-8939-1e802bc0da18	JZB114306-20	26/01/2022	initial
48e9ca93-7976-4986-b02a-980f65b2e419	AC MODULE V4, PANTHER	99-005607-04	c69e58a5-4735-407e-ab33-0c8cecbc1bbe	JZB030153-23	26/01/2022	initial
e5f00a14-e368-478f-922f-797c99ac4a02	CP6000, HEAD UNIT, W/DISPLAY, NO CAMERA, 32A 5.5M, DUAL	99-006602-01	4742592d-1f3e-4a90-8e35-077d57b94c8b	JZB664350-01	26/01/2022	initial
b2c67c4a-8f33-439a-bcaf-915c62a6a183	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL CABLE-T2-32A-5.5M-15118	99-006602-03	c2c8dad3-0b86-45ab-9e62-8a72ea0add65	JZB129845-97	26/01/2022	initial
418797d6-1263-45c2-9063-b601f673adbf	CPE250, EU, 2 CABLE CCS1/CCS2,DVT	99-002703-08	55511cac-5513-499d-a914-7f00d35cf1aa	JZB714526-02	26/01/2022	initial
b585c2bf-6c28-4cc3-97f7-377a9dfca669	CPE250, EU, 2 CABLE, EVT	99-002611-05	97d5b61d-e9f9-4e2e-9c92-adbbd40797f6	JZB125517-12	26/01/2022	initial
4f868864-c743-4e90-a7c4-135b1079d5bc	CPE250, EU, 2 CABLE, IV SIGNS	99-002639-07	72221aec-9a1b-4aa7-ae19-b4b8814eb1be	JZB665602-04	26/01/2022	initial
b8db4ae6-85aa-4d84-bb32-1f94ff2b5f2f	CPE250, EU, CCS1/CCS2, MB	99-002713-07	79f3c954-8094-44e3-90cf-0d2d70249efb	JZB843073-97	26/01/2022	initial
5c44dbed-3293-444a-bdc1-4d0ebb630847	CPGW-EU	99-004122-01	59d99495-5e4a-4c26-be9d-a35cdf73df6c	JZB296183-95	26/01/2022	initial
27edbddd5-719f-49bc-a47a-ea7722560d18	CP4320-MTR-UNIT	99-003206-02	7f3367f5-5cf8-41cd-9e25-a207e312b629	JZB914904-00	26/01/2022	initial
a892a5bf-f55d-4322-962b-6bdce4526689	CP6000, HEAD UNIT, W/DISPLAY, NO CAMERA, SOCKET, DUAL	99-006605-01	01cda1b2-088c-40d8-847f-38da1f2f835c	JZB574500-10	26/01/2022	update
34ac4cab-5633-4e67-802a-c1c6610e8f18	CPE250, EU, CCS1/CCS2, MB	99-002713-08	e19a30e1-6eaa-4873-969f-e5b546ab02e6	JZB009222-14	26/01/2022	update
9d3c1b6a-3e0c-4b83-8c8e-90ecabc64c69	CPGW-EU	99-004118-01	115ff735-aa00-44e2-ade2-24906a22fbda	JZB861618-00	26/01/2022	update
c7561b52-618f-451c-afb6-33b7210588f5	CPE250C-CCS1-CCS2-EU	99-002703-01	01c71f7b-7689-4146-a9e5-2ca39abd7742	JZB955530-96	26/01/2022	update
2d564807-dd9f-4a2d-a924-77744f7098b4	CP4310-UNIT	99-003205-01	cbf2e760-ec0e-4aa6-a5eb-64e223554e94	JZB448644-94	26/01/2022	initial
a892a5bf-f55d-4322-962b-6bdce4526689	CP6000, HEAD UNIT, W/DISPLAY, NO CAMERA, SOCKET, DUAL	99-006605-01	40e6865a-4297-4351-a3c3-b6f520d34228	JZB878676-75	26/01/2022	initial
ecfbda15-7044-4589-9d6e-25839294797e	CP6K-HEAD ASSY-EU/UK-CCOM-8IN DISP-NO CAM-CPIM-DUAL SOCKET	99-006605-03	95e3cb8e-f154-4d79-bb9a-e2335da9b823	JZB924324-01	26/01/2022	initial

Reference number	Names	Identifiers	Dossier UUID	Submission number	Submission date	Submission type
43da0b11-ea02-45aa-ac48-958f3de56b46	CPE250, EU, 2 CABLE CCS1/CCS2, EVT	99-002703-02	8b00c940-5fa6-4b7b-9c07-e6f85f97b912	JZB730694-95	26/01/2022	initial
d14ab546-f195-408d-b83a-02cf3f147553	CPF32-T2-EU	99-004121-01	30e6f6d7-e31b-4cde-83ec-401733765fa8	CES933437-28	08/11/2021	initial
eea15c64-5050-49a9-97e3-0ac6b79ba9d8	CPH32-T2	99-003002-01	7ac557dc-8194-4e21-bd08-005869c6cea3	CES278900-36	08/11/2021	initial
bbfe43ea-efeb-482b-81f4-83b4b7a0eb14	CP4120-MTR-UNIT	99-003203-02	663e1b10-4e08-4231-a374-4e045cbeb099	CES220689-35	08/11/2021	update
10655547-10a8-40ab-bf92-ea2dda35592a	CP4303-ACTK	99-003216-01	ab235c80-ad22-4807-a1ea-339ef77dd076	CES703297-25	08/11/2021	update
c7561b52-618f-451c-afb6-33b7210588f5	CPE250C-CCS1- CCS2-EU	99-002703-01	a42a40b7-439b-4c82-aa04-9fc8f61597ed	CES644118-37	08/11/2021	initial
d14ab546-f195-408d-b83a-02cf3f147553	CPF32-T2-EU	99-004121-01	fd195f78-4349-4bc0-8c14-d4fb5fd895d4	CES557539-23	08/11/2021	update
e0bb5db6-a3a0-48cb-acf7-8ad5c90267cb	CP4110-UNIT	99-003201-01	bc5278d5-4f39-4372-8d85-cfb1d6bc0d80	CES634892-21	08/11/2021	update
444e5512-8375-48b1-8492-9ff5e11e8b6f	CP4300,Dual Port,Cabled,T2,Pede stal	99-003213-01	bd0528e9-8c9b-4a23-8b23-d9a0219b1945	CES102441-53	08/11/2021	update
21099736-da60-4759-a357-fac8aeb7c3e6	CPH32-T2-EU	99-003012-01	8ee96222-02e3-4577-ab07-abef43ecd816	CES184920-41	08/11/2021	update
fb29f63f-80aa-4c0f-8e5f-03f355080386	CP4110-SH-UNIT	99-003202-01	034d63a7-3512-4002-aa4a-fafc51141adc	CES826490-20	08/11/2021	update
1d554935-fd80-4b83-a48c-d8531b22f39b	CP4120-SH-UNIT	99-003204-01	07dc896d-72d1-4acc-83f9-d657f487f891	CES023358-43	08/11/2021	update
1b0441e3-c00d-4809-8d37-338013ec8fc5	CP4300,Single Port,Cabled,T2,Pede stal	99-003212-01	10985dc0-4c7e-4d16-9def-167d8088c31e	CES556759-19	08/11/2021	update
49ad46a5-32ed-420e-b981-82e9514cbd27	CPE250, EU, 2 CABLE, EVT	99-002611-04	363f8170-f727-4fac-b020-ded415bf87f9	CES515356-32	08/11/2021	initial
9d3c1b6a-3e0c-4b83-8c8e-90ecabc64c69	CPGW-EU	99-004118-01	257463d4-e7e1-464e-99e6-e0a3251dd018	CES298516-30	08/11/2021	initial
01ae45f2-8d1f-423a-8fcc-fee167a8ffe	CP4320-UNIT	99-003206-01	6a4dbcfe-cb62-4014-aa64-10d0fb9e9ced	CES429857-19	05/11/2021	initial
31a824c4-7926-4577-89b6-e53a150f05e3	CP4110-MTR-UNIT	99-003201-02	1de310b3-f302-4138-a9d1-182d9eb8fb5b	CES089349-26	05/11/2021	update
10655547-10a8-40ab-bf92-ea2dda35592a	CP4303-ACTK	99-003216-01	0e58c0d4-7797-44e8-b7cf-830b64c6227f	CHU103688-26	01/07/2021	initial
ff961153-2461-419c-ad7e-26c3f3288a19	CPE250, EU, 2 CABLE CCS1/CCS2, EVT	99-002703-03	c2a6e825-1acc-4888-8577-0f72f74f57cf	WTX646481-68	09/06/2021	initial
e171117e-c906-45bc-bb19-f76132a2daaf	CPE250, EU, CCS2/CHD, SM	99-002717-07	53101155-b3e7-4c0f-af94-6951e53aeb96	WTX963803-76	09/06/2021	initial

Reference number	Names	Identifiers	Dossier UUID	Submission number	Submission date	Submission type
34ac4cab-5633-4e67-802a-c1c6610e8f18	CPE250, EU, CCS1/CCS2, MB	99-002713-08	1104bdac-524a-499a-93c9-b3302d1cb5ea	WTX693083-71	09/06/2021	initial
21099736-da60-4759-a357-fac8aeb7c3e6	CPH32-T2-EU	99-003012-01	50ed452c-b923-4878-ad14-8b19ca0f5e84	WTX801177-77	03/06/2021	initial
fb29f63f-80aa-4c0f-8e5f-03f355080386	CP4110-SH-UNIT	99-003202-01	64842944-7b6e-4cff-9efd-e2c47f576768	TAJ173616-43	26/05/2021	initial
1b0441e3-c00d-4809-8d37-338013ec8fc5	CP4300,Single Port,Cabled,T2,Pedestal	99-003212-01	37544cde-fa37-4298-a7d2-278220d78122	TAJ884488-12	26/05/2021	initial
1d554935-fd80-4b83-a48c-d8531b22f39b	CP4120-SH-UNIT	99-003204-01	e64cabdb-0221-4c26-b121-22af77db088a	TAJ423657-33	26/05/2021	initial
31a824c4-7926-4577-89b6-e53a150f05e3	CP4110-MTR-UNIT	99-003201-02	cec3ff1b-7781-4668-a479-369103510622	TAJ501016-52	26/05/2021	initial
f3128ea0-db2f-461f-aeda-511cd2ad5e7f	CP4120-UNIT	99-003203-01	22a206cc-6b7d-490d-ae2e-f112501d3c1d	TAJ021417-55	26/05/2021	initial
bbfe43ea-efeb-482b-81f4-83b4b7a0eb14	CP4120-MTR-UNIT	99-003203-02	5116d04d-74c1-4e8b-b4dc-e8a3629a6747	TAJ159505-37	26/05/2021	initial
e0bb5db6-a3a0-48cb-acf7-8ad5c90267cb	CP4110-UNIT	99-003201-01	d9c3545c-e933-4bad-9323-098a7bdc7e1a	TAJ037025-46	26/05/2021	update
444e5512-8375-48b1-8492-9ff5e11e8b6f	CP4300,Dual Port,Cabled,T2,Pedestal	99-003213-01	b3b8c871-5274-4623-a69c-019ba8255127	TAJ955264-21	26/05/2021	initial
1b0441e3-c00d-4809-8d37-338013ec8fc5	CP4300,Single Port,Cabled,T2,Pedestal	99-003212-01	4816ebdf-fff8-4de6-87b5-a5788301d7ba	TAJ240567-40	26/05/2021	update
0173b51a-3042-47dc-994c-8e9b2c8ec666	CPF32, CPF32-T2	99-004110-01	643a2b9d-0b16-4e34-ad58-ad72d7fa2b65	GQZ731393-94	26/02/2021	initial
e0bb5db6-a3a0-48cb-acf7-8ad5c90267cb	CP4110-UNIT	99-003201-01	dc525b76-ca3d-4c61-97b9-14dbcfffb6e2	UDM155342-32	10/02/2021	initial